

**NORTH BIHAR POWER DISTRIBUTION COMPANY LIMITED , PATNA**  
(Reg. Office- Vidyut Bhawan, Bailey Road, Patna)

(Department of Operation & Maintenance)

Letter No. 777/

Dated 7/9/13

XI/O&M/1111-34/2013

Phone No. 0612-2504194

Fax No. 0612-2504509

Email- ceomnbpdc@gmail.com

From,

**B.K. Choudhary**  
**Chief Engineer (O&M)**

To,

All DGM cum Electrical Superintending Engineers  
Electric Supply Area  
All Electrical Superintending Engineers  
Electric Supply Circle  
All Electrical Executive Engineers  
Electric Supply Division

**Sub: - Inspection and maintenance of 33/11 KV PSS**

**Ref: (i) This office letter no 103, dated 05.04.13**

**(ii) This office letter no 125, dated 20.04.13**

**(iii) This office letter no 69, dated 29.05.13**

Sir,

Please refer to letters under reference on subject noted above through which it has been requested in regular way to inspect the 33/11 KV PSS and submit the report thereafter to take immediate necessary steps to prevent failure of Power Transformers & others equipments. But after a lapse of more than three months the report regarding same is awaited. However report regarding status of Transformer Oil & Top up, Earthing, DC System, VCB installation, AB Switch installation & L.A. installation are being collected through mobile, which are unsatisfactory, Whereas VCBs, AB switches, G.I. Earthing pipes are available in stores and it is being diverted as required by you from one store to another in case of non-availability. Non-Submission of report after inspection and lack of preventive measures are matter of concern which has been viewed seriously.

You are therefore requested to inspect all PSS under your jurisdiction within a week and take immediate preventive measures to prevent failure of Power Transformers.

**This is Urgent.**

~~9/9/13~~  
~~10/09/13~~

Yours Faithfully

**B.K. Choudhary**  
**Chief Engineer (O&M)**

CC: OSD to MD, NBPDC for information.